

ECS Configuration Change Request

Page 1 of 2

Page(s)

1. Originator Robert Cole	2. Log Date: 7/18/02	3. CCR #: 02-0598	4. Rev: -	5. Tel: 301-925-0799	6. Rm #: 2110C	7. Dept. SE/HW
8. CCR Title: Submit Test Executable to upgrade Axis firmware for security vulnerabilities						
9. Originator Signature/Date /s/ Robert Cole 7/18/02			10. Class II	11. Type: CCR	12. Need Date: 7/19/02	
13. Office Manager Signature/Date /s/ James R. Mather 7/18/02			14. Category of Change: Update ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Emergency	
16. Documentation/Drawings Impacted: N/A			17. Schedule Impact:		18. CI(s) Affected: DIPHW	
19. Release Affected by this Change: N/A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input checked="" type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other: ECSed34495						
23. Problem: (use additional Sheets if necessary) Security vulnerabilities exist under the current configuration and firmware level of the Axis print server which is used with the Internem label printers in PDS. The following vulnerabilities have been identified by the ISS security scan: SNMPv1 trap or request handling SNMP_Set guessed community name and changed system information FTP daemon with no password SNMP_Set used public community name to change system information						
24. Proposed Solution: (use additional sheets if necessary) Issue the attached Test Executable to resolve these vulnerabilities. The attached sheet details the procedure to upgrade the Axis firmware and make the necessary configuration changes. This will be released as patch ISS.01 Distribute the firmware file 54xp.bin to all sites. The cksum output for this file is: 1876557108 1160501 54xp.bin						
25. Alternate Solution: (use additional sheets if necessary) Accept the risk associated with the above vulnerabilities.						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)						
27. Justification for Emergency (If Block 15 is "Emergency"): NCR ECSed34495 is at severity level 2. This issue is currently ranked at 15 in the OPS priority list.						
28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:				30. Work Assigned To:		31. CCR Closed Date:
32. EDF/SCDV CCB Chair (Sign/Date): /s/ Byron V. Peters 7/18/02			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. M&O CCB Chair (Sign/Date): s/s Pamela Johnson 7/18/02			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: 02-0598

Rev: - Originator: Rob Cole

Telephone:

Office:

Title of Change: Submit Test Executable to Upgrade Axis Firmware for Security Vulnerabilities

Issue: Several security vulnerabilities have been identified with the current Intermec label printer and Axis print server configuration in the PDS subsystem:

- SNMPv1 trap or request handling
- SNMP_Set guessed community name and changed system information
- SNMP_Set used public community name to change system information

Fix: The following actions should be completed to resolve the above vulnerabilities:

Upgrade Axis Firmware:

An upgrade to version 6.0 of the Axis 540+ print server firmware will resolve the SNMPv1 trap or request handling vulnerability.

1. Obtain a copy of the file 54xp.bin. This file will be distributed to the DAACs via the Configuration Management software distribution process.
2. Connect to the Axis print server using FTP and login as root.
3. Enter binary at the FTP prompt to change to binary mode transfer
4. Enter put 54xp.bin flash to upload the new firmware to the print server.

After the file is transferred, the print server will automatically restart running the new firmware

Modify Configuration File

Modifications to the Axis configuration file will resolve the other vulnerabilities.

1. Download the Axis configuration file to a host computer.

Login to the print server using the command ftp IP_ADDR where IP_ADDR is the IP address of the print server. Enter root at the user id prompt and pass at the password prompt.

Download the configuration file from the print server using the command get config.

2. Edit the configuration file

Change the 3rd and 4th lines in the General menu to the following:

```
ROOT_PWD.      : <root_pwd>
USERS.         : u:<user_name>;p:<user_pwd>
```

Note: The root and user passwords chosen for the above lines can be the same. Ensure that passwords are at least eight characters and contain an uppercase letter, number and special character among the first 8 characters.

Change the 1st, 2nd, 4th and 5th lines in the SNMP menu to the following:

```
READ_COM       : <snmp_pwd>
WRT_COM.       : <snmp_pwd>
TRAP_COM.      : <snmp_pwd>
SYS_NAME.      : <snmp_pwd>
```

where <snmp_pwd> is a password chosen according to the above guidelines. A separate password can be used for each line.

3. Upload the modified configuration file to the print server using the command put config CONFIG. The second argument (CONFIG) must be entered in capitals in order to save the settings permanently.

4. Restart the print server using the command `get hardreset`.